Of L



PATENT Attorney Matter No. 6454-66361-01

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re application of: Keefer et al.

Date Mailed June 29, 2007

Patent No. 7,094,275

Issued: August 22, 2006 **Application No.** 10/620,262

Filed: July 14, 2003

Confirmation No. 8753

For: MODULAR PRESSURE SWING

ADSORPTION APPARATUS

Examiner:

Art Unit: 3744

Attorney Reference No. 6454-66361-01

Certificate

JUL 1 0 2007

of Correction

COMMISSIONER FOR PATENTS P.O. BOX 1450 ALEXANDRIA, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION

The following printing errors were noted in comparing the printed patent with the papers in the attorneys' files:

In the Specification:

Column 1, Line 26, "cl BACKGROUND OF THE INVENTION" should be a section heading and should read -- BACKGROUND OF THE INVENTION --

Column 2, Line 44, "cl SUMMARY OF THE INVENTION" should be a section heading and should read -- SUMMARY OF THE INVENTION --

Column 8, Line 63, "are" should read -- arc --

Column 9, Line 20, "along" should read -- long --

Column 20, Line 23, "3711B" should read -- 371B --

Column 24, Line 14, "face..." should read -- face. --

JUL 1 0 2007/

All of the above errors are attributable to the Patent Office, and a Certificate of Correction is enclosed in duplicate to make formal notice of the errors in the referenced patent.

Respectfully submitted,

KLARQUIST SPARKMAN, LLP

One World Trade Center, Suite 1600 121 S.W. Salmon Street Portland, Oregon 97204

Telephone: (503) 595-5300 Facsimile: (503) 595-5301

cc: Docketing

5

Ву

Jefffey B. Haendler Registration No. 43,652 Staple Here Only ŧ

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 7,094,275

DATED : August 22, 2006

INVENTOR(S) : Keefer et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Specification:

Column 1, Line 26, "cl BACKGROUND OF THE INVENTION" should be a section heading and should read -- BACKGROUND OF THE INVENTION -- Column 2, Line 44, "cl SUMMARY OF THE INVENTION" should be a section heading and should read -- SUMMARY OF THE INVENTION -- Column 8, Line 63, "are" should read -- arc -- Column 9, Line 20, "along" should read -- long --

Column 20, Line 23, "3711B" should read -- 371B --

Column 20, Line 23, 3711B Should lead -- 371B --

Column 24, Line 14, "face..." should read -- face. --

Staple Here Only

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 7,094,275

DATED : August 22, 2006

INVENTOR(S) : Keefer et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Specification:

Column 1, Line 26, "cl BACKGROUND OF THE INVENTION" should be a section heading and should read -- BACKGROUND OF THE INVENTION -- Column 2, Line 44, "cl SUMMARY OF THE INVENTION" should be a section heading and should read -- SUMMARY OF THE INVENTION -- Column 8, Line 63, "are" should read -- arc -- Column 9, Line 20, "along" should read -- long -- Column 20, Line 23, "3711B" should read -- 371B -- Column 24, Line 14, "face..." should read -- face. --